U.S. Department of Transportation
Federal Aviation
Administration

B.C.

Memorandum

1806

oject

rom.

To

ACTION: Safety Alert "Long-Eze" Amateur-Built Airplanes

Date

JAN 2 8 1985

L. B

Sandy DeLucia

Reply to Attn. of:

Acting Manager, Aircraft Manufacturing Division, AWS-200

4.4

All Flight Certification Divisions All Flight Standards Divisions My

This office has received information regarding a potential hazard on the "Long-Eze" amateur-built airplanes. The head rest assembly does not appear to provide protection for the pilot in the event of an accident that culminates with the inversion of the airplane.

All builders, prospective builders, and operators should be apprised of this potential hazard. We are enclosing a copy of the correspondence that was received from the Minneapolis GADO.

Please disseminate this information to all personnel involved in the airworthiness certification of amateur-built aircraft.

Attachment

RECEIVED
Los Angeles Area Office

FEB 07 1985

Action 180 L
Date Ans. \_\_\_\_\_



U.S. Department of Transportation

Federal Aviation Administration

## Memorandum

GENERAL AVIATION DISTRICT OFFICE 6201 - 34th Avenue South Minneapolis, Minnesota 55450

Subject

ACTION: Recommendation for Accident Prevention, Order 8020.11, Paragraph 268

Date

December 27, 1984

Original Signed By

From Andrew Detroi

Manager, Minneapolis GADO

Reply to Attn of

Detroi:725-3341

To Manager, Aircraft Certification Division, ACE-100 Thru: Manager, Flight Standards Division, AGL-200

On June 29, 1984, an Andrich/Lee Long-EZ owned and operated by Howard Lee, of Camarillo, California, experienced power failure after liftoff at 400 feet AGL. The pilot made a 180° turn and returned to another runway. He landed long, left the side of the runway to avoid going off the end and proceeded diagonally across a wheat field. The aircraft nose gear collapsed and the aircraft went inverted. The canopy shattered and the pilot's headrest broke off during the crash.

This is the second Long EZ aircraft accident in the State of Minnesota in three years that the aircraft went inverted and the headrest broke off. The result was one fatal and one with minor head injuries.

Due to lack of protection during rollover accidents, it is recommended that the headrest be either re-enforced or made out of more durable material to afford crashworthiness protection for the pilot.

Discussing this situation with Mike Mellville, Rutan Aircraft Factory, he assured me that the factory would re-evaluate the structural integrity of that area.

#

ASF-100 Accident Investigation Division
AWS-200 Aircraft Manufacturing Division
Rutan Aircraft Factory (Mike Mellville

Rutan Aircraft Factory Building 13 Mojave, CA 93501)