

## 23





*The Cessna 152's Lycoming O-235-L2C can develop high oil consumption, most often because of barrel warpage and oil-control ring expander coking.*

*(Continued from previous page)*

engine should not be operated any longer than necessary on straight (non-dispersant) mineral oil. As soon as a newly overhauled engine has broken in—perhaps in as little as five or six hours—the oil should be changed over to a good-grade semi-synthetic (Aeroshell 15W-50) or full synthetic (Mobil AV 1) for good oil control over the life of the engine. (Obviously, if the oil-ring expander is already gummed, switching to one of these oils won't necessarily help matters. Once the gum has formed, it's too late.)

A poor overhaul, incidentally, will only accelerate ring gumming. If choke (barrel taper) is not properly restored, or if the barrel is out of round (as most barrels eventually become)—or if the barrel warps in service—there will be localized areas on the cylinder wall where the rings (compression *and* oil-control) won't be able to conform to the surface, and where, as a result, hot gases passing under the rings will scorch the oil on the cylinder wall. The burned oil will ultimately clog the oil-control ring groove and/or expander and/or drainback vents. Oil consumption then goes on a long, steady slide.

The design of the oil-ring expander itself plays some role in the gumming-up tendency. Two styles of ring expander are currently in use (in aviation): a wavy style and a coiled style. The coiled style is by far the most common, although some are more tightly coiled than others. When the oil control ring is of the center-vented style, efficient oil drainback depends on having a lot of open space for oil to flow through, and wavy expand-

ers offer better performance in this regard. John Schwaner of Sacramento Sky Ranch (a popular West Coast overhauler) agrees, saying: "The lack of free space of the coil expander results in rapid sludge buildup if there is any burning of oil on the cylinder wall. We often see coil-style expanders completely sludged up in many Continental and Lycoming engines."

One engine for which a wavy-type expander is available is the Lycoming O-235-L2C/N2C. Schwaner highly recommends the wavy expander for this engine. "When removing the cylinder from an -L2C engine for high oil consumption, look to see if the oil control ring is stuck due to sludge buildup. For a temporary repair, you can simply replace the oil control ring with a new one, preferably with the wavy expander, and re-install the cylinder."

The repair is temporary, Schwaner says, because if blowby scorching is occurring, barrel distortion (which is the source of the problem) will have to be removed by regrinding the barrel. Simply deglazing the barrel won't do the trick.

Until wavy oil-ring expanders are available for every engine model, the best advice is simply: Use a good grade of oil, and *change oil often*. (Users of full-synthetic oils can go longer between changes than mineral-oil users, obviously.) At overhaul time, insist on a top-notch barrel grind to restore roundness and choke; don't return a marginal jug to service and expect good oil control. And finally: Switch to a semisynthetic or fully synthetic oil *as soon as possible after break-in*. After a ring expander gums up, it's all downhill from there.